

Consumer Aftercare Guidelines

January 15, 2026

Following Installation

Allow 3 – 7 days for ClearPlex to properly cure. During this period, avoid rain, high speeds, washing, waxing, and wiper usage. If the average daily temperature falls below 55 F (13 C), allow an additional 2 days for proper curing.

If the film is exposed to staining contaminants such as bird droppings, tree sap, or similar substances during the curing period, promptly remove the stains by spot-treating only the affected areas with Madico Endurance Surface Prep or Isopropyl Alcohol. Avoid applying cleaning agents directly along the perimeter film edges.

Do not attempt to pierce any water bubbles during the curing period, as this will cause damage to your film that is not covered by the warranty.

Full curing may take up to 30 days. During this time, it is normal for haze and condensation to be noticeable. In most cases this dissipates within 7 days. Do not attempt to remove haze, condensation, or attempt to address any edge lifting.

After 30 days, if any follow-up work is required, the installing dealer is the only authorized person or entity permitted to perform this work. Contact your installing dealer with any concerns.

ClearPlex Film Care and Maintenance

ClearPlex features a durable scratch-resistant coating, however, proper care is essential to maintain your film in good condition:

- Cleaning:
 - Hand wash your vehicle with Madico® Endurance™ Rinseless Power Foam Car Wash or similar.
 - Promptly remove tough stains like insects, tree sap, or similar contaminants with Madico Endurance Surface Prep or isopropyl alcohol.
- Ceramic coatings and sealants:
 - Many ceramic coatings are formulated with harmful petroleum-based solvents that can damage the film. These types of ceramic coatings must not

be used on ClearPlex. Only use ceramic coatings formulated with a non-petroleum, neutral carrier like Endurance TruCeramic or similar.

- An approved ceramic coating may be applied during installation or at any time afterward to extend the life of the film.
- Sealants may be used to enhance the hydrophobic properties and overall longevity. Using a sealant will reduce the need for wipers which reduces daily wear. Only use approved sealants on ClearPlex, like Madico Endurance Glass Clean & Protect or a wax-based sealant like Rejex® or similar.
- Wiper use and care:
 - Remove debris from windshield wipers before use. Replace damaged wipers immediately. Debris can scratch the film.
 - ClearPlex film may be lightly polished to remove wiper marks using a product like Madico Endurance Primer Polish or similar. After polishing, treat the surface with an approved ceramic coating or sealant. For best results, contact your installing dealer to correct wiper marks and apply a new coating.
 - Always use washer fluid when operating wipers. Never run wipers dry, as this may cause damage.
- Items and conditions to avoid*:
 - Automatic or commercial car washes.
 - High-pressure washer, high powered pressure steam, and/or a power washer.
 - Abrasive cleaners or materials.
 - Ice scrapers or sharp tools.
 - Exposure to thermal shock (sudden excessive heat or cold).

**These items and conditions are not covered under the Madico ClearPlex Warranty and will void the warranty. Please refer to the Madico ClearPlex warranty for full details.*