

Storage

- Films must always be kept dry when not being fitted onto the glass.
- Do not store on end.
- Recommended storage temperature is between 40 °F (5 °C) to 100 °F (38 °C). Storage for prolonged periods outside this range will damage the film or its coatings.
- Do not store at temperatures above 140 °F (60 °C) or below 32 °F (0 °C)
- Store the material in a climate-controlled room for a minimum of 24 hours before application.
- Store film within the protective polyester sleeve and within the box.
- Keep film on the core suspended in the box by the end caps. This prevents the material from sliding or telescoping off the core.
- Retain roll boxes for storage purposes.

Handling

- Heavy gauge polyester films will cause cuts.
- Madico recommends using cut-resistant gloves when handling these films.
- Avoid impacting or dropping.